



How do you measure a box?

1. Listed dimensions are always inside dimensions.
2. The first dimension is length. Length is always the longest side of the box that has a flap.
3. The next dimension is width. The width side also has a flap, but is always the side shorter than the length.
4. Height is the only dimension without a flap. The height measurement does not include the flaps.



4 x 4 x 8
L x W x H



18 x 12 x 10
L x W x H